





The aircraft received damage to its forward right-hand side fuselage skin and support structure. SOAR conducted a turn-key repair on schedule and on budget.

Project scope included removal of damage, frame and skin installations, final checks and certification.

For a graphic presentation of this repair please visit: www.sourceoneaircraftrepair.com.