


## BOEING 767-300 REPAIR & MODIFICATION, MEDINA, SAUDI ARABIA



The aircraft landed with one main gear retracted. The lack of local infrastructure did not support the heavy structure repair & pylon modification that was required.

SOAR was contracted to repair the

aircraft to serviceable condition for ferrying.

Work scope included fuselage damage repair, engine strut replacement & engine strut wing interface modification.

For a graphic presentation of this repair please visit: [www.sourceoneaircraftrepair.com](http://www.sourceoneaircraftrepair.com).