




MD-82 DAMAGE EVALUATION, KANDAHAR, AFGHANISTAN



During a landing in windy conditions, the aircraft's right hand wing outboard section made contact with a runway light fixture causing major damage to the outboard section and common structure of the right hand wing.

The Source One Aircraft Repair (SOAR) team was contacted and the damage evaluation was efficiently and accurately completed on the NATO Base facility in Kandahar, Afghanistan.

For a graphic presentation of this repair please visit: www.sourceoneaircraftrepair.com.